


















# GRAVOGRAPH NEW HERMES

## Special Shapes


1. The Discovery Level of Gravostyle gives you the ability to draw special shapes and create special effects on your work. It also gives you the ability to cut out special shaped pieces. When you are in the Select Mode you will see the Special Shape tool Bar.



2. As throughout the rest of the program, pressing the F2 key while performing an action will bring up a window to perform that action. The Special Drawing tools are no exception. On several of these shapes if you press and hold the Control Key down when you click on the button, you will get even further control.


	Markers		Ellipses
	Rectangles		Circles
	Polygon		3 Point Circles
	Stars		Arc
	Arrows		3 Point Arc
	Curved Lines		Drilling Holes
	Double Lines		Symbols Library
	Straight Lines		

3. To see an example of the screen using the F2 feature while you are drawing a rectangle click on the Rectangle button. Move the cursor down into your material area and click and hold it down while you drag cursor across the material and start drawing the rectangle. Then press the F2 key. The precision screen will come up.




As you can see it gives you far greater control of your object. (i.e. size to 0.0001 of an inch, location and how you want the corners to look)


- For an example, press and hold the Control Key down and click on the Double Line button.



You can control the corners, how far the lines are apart and how to close off the ends if you want.

- Click on the Drilling Hole button and the Drilling Points Page will come up. Insert the size of the drilling tool you are using and where you want the holes located. Once you select the button for the location of the holes, the window will pop up to position them from the edge of the material. If you wish to place them elsewhere on your work, do not click on any button, just press the OK button you will notice that your cursor changes, now where ever you click you will place a drill hole.



6. If you wish to place a symbol on your work click on the  button and the symbols library screen will pop up. Find the file location for your symbol, click on it and press the OK button. You will see a dotted line square around your cursor. Click on the location you want to place the symbol.

