

# Appendix

## Hot Keys

F1	Help
F2	Precision dialog
F3	Snaps
F4	Preview
F10	Options
Ctl-1	XY View
Ctl-2	YZ View
Ctl-3	XZ View
Ctl-4	Engrave View
Ctl-5	ISO View
Ctl-6	3D dialog
Ctl-A	Redo last operation
Ctl-C	Copy selection to clipboard
Ctl-L	Select All objects in select mode
Ctl-M	Open model file
Ctl-N	New file
Ctl-O	Open file
Ctl-R	Fast redraw
Ctl-S	Save file
Ctl-V	Paste selection from clipboard
Ctl-W	Redraw
Ctl-X	Cut selection to clipboard
Ctl-Z	Undo last operation
Del	Delete selection